

# Machine troubles during user-time in SPring-8

05 Feb. 2002

SPring-8 accelerator div.

T. OHSHIMA

- About SPring-8
- Operation statistics
- Troubles in 2001
  - RF                      vacuum leakage from absorber
  - Mag                     water leak from tube
  - Beamlines            rfbpm of insertion devices
- Detection of abort source
- Delay in refill the beam
- Conclusion



# SPring-8 is

**Electron storage ring**

**8GeV 100mA life ~130hr for multi-bunch op.**

**Circumference 1436m**


**Emittance ~6nmrad**

**Coupling < 0.1%**

**Injector**

**1GeV Linac**

**8GeV Booster Synchrotron**




# Operation statistics

year	tuning	user	refill	down	total
1997	304	906	50	26	1286
1998	1458	2512	110	110	4190
1999	1624	3275	95	57	5052
2000	1815	3193	70	89	5168
2001	1277	4033	59	87	5456

Commissioning

Optics changed

Introducing LSS




**10 operation cycles in 2001**  
**3 or 4 weeks/cycle**

**Injection:**  
**once / day (multi-bunch op.)**  
**twice / day (several bunch op.)**

# Example of stored current

10th cycle 2001



No fault for 7 days + 6 days = 13 days (335hrs)

# Troubles in 2001

type	failure	fault time(hr)
RF	14	44.7
magnet	10	16.7
beam line	11	10.7
safety	1	6.5
earthquake	1	2.7
lightening	1	1.2
other	5	3.6

Total down time 87.1hrs

~2% to user time

Mean time between fault 58.4hrs


RF		Magbet		beamline	
arc	4	flow sw	6	rfbpm at ID	5
reflection	3	PS err	3	miss operation	1
kly vac	3	water leak from tube	1	vacuum leak	1
kly PS err	2			err in PLC for safety	1
kly over curr	1			air pressure down for GV	1
absorber	1			limit sw of door	1

# Water leakage to vacuum from SR absorber of RF station

\* ccg2 (Pa)


—●— current (mA)

C station pressure and current




- Sudden pressure increase -> beam abort
- H<sub>2</sub>O was dominant in gas components
- Found leak from absorber and Change to spare
- Down time: 36hr






- OFHC+H<sub>2</sub>O+SR  
-> corrosion
- Another leak at other station -> early start of summer shutdown
- Replace all absorbers at RF section with Newly designed absorbers



# Water leakage from tube



Cooling water was leaked  
from Q magnet

Down time 4.9hrs

Possible sources

\*Growth of small cut

\*Radiation damage


near injection point

greater than  $10^6$  Gray for 3 years

radiation shield will be installed



# rfbpm at ID section



- prevent SR irradiation of unexpected place

window : 0.5mm (horizontal) 0.25mm (vertical)

abort the stored beam within a few ms


- Work well

Earthquake

Orbit drift induced by error in magnets

- 23 IDs are in operation
  - Wide bandwidth of rfbpm
- > sensitive to noise


-> new system  
abort when 2 rfbpms fire



- Beam Interlock Module (BIM)

transfer abort signal to RF stations to cut the power

distinguish first arrival of interlock signal





# Detection of abort source

- All data : saved in Data Base
- Loss of beam ->
  - Voice alarm
- Possible source is presented in GUI
  - Check the interlock signal
  - Check which signal arrives first
- Confirmation & Reset interlock
- Restart beam operation

Interlock Status			
File	Tool	Special	Help
			2002/01/15 19:56:58
Abort Time	2002/01/15 19:56:25		
Abort Current	4.525 [mA]		
Abort Source	BL09IN: BL FCS		
Beam Abort Status			
BL Interlock	BL PLC	Abnormal	
	ID rf BPM	Normal	
	Fast Closing Shutter	Abnormal	
Vacuum Interlock	Normal		
Safety Interlock	Normal		
Beam Abort Switch	Normal		
Emergency Stop	Normal		
Beam Abort First Arrival			
Beam Interlock Module	BL09IN		
ID RF BPM Beam Abort	None		
Among RF Station Interlock	B Station		
RF Station	A	BIM	
	B	BIM	
	C	BIM	
	D	BIM	
RF Interlock Abort Status			
Station	Machine	Safety	Emer. Stop
A	Abnormal	Normal	Normal
B	Abnormal	Normal	Normal
C	Abnormal	Normal	Normal
	Abnormal	Normal	Normal
SR Magnet Alarm Status			
Magnet Name			Alert Count
B Magnet			None
Q Magnet			None
Sx Magnet			None
St Magnet			None
Skew Magnet			None

- Delay in refill was 8hrs in 2001

- Warm-up of injectors: 30min before injection

- Linac

  - Modulator (thyatron over current ...)

  - pressure increase of waveguide or cavity

  - Gun (burn out of cable of HV ...)

  - Energy drift -> lead to loss of injected beam

    - <- energy compensation system

      - temperature stabilization of cooling water, waveguide

- Booster synchrotron

  - Large reflection from cavity

# Conclusion

- Stable operation at SPring-8

ex. No fault for 335hrs at 10th cycle '01 user time

- Some troubles & cure

leak from absorber at RF, water leak from tube of Mag,  
malfunction of rfbpm of ID . . .

- Detection of abort source

identify the source within about 15min.

- Reliable => to satisfy user's request

reduction of down time

stabilization of beam orbit






photon  
absorber

tube of cooling  
water

injection  
line



- Usually tubes are located inner side of tunnel
- Near injection point there is no space so the tubing is located **outer side**

# Voltage drop of power line


## ■ Voltage drop

< 15% ==> No trouble

> 15% ==> fault in Q PS, cooling pump ...

## ■ lightning to electric cable of power company

number of voltage drops (>15%)  
'99 Jun to '01 May




summer shutdown

Jul. - Aug.

Down time

'00 : 2 times 5.0hr

'01 : once 1.2hr



Ground motion ->

change in circumference

misalignment of magnets

Horizontal beam oscillation

-> abort by rfbpm @ ID

## Down time

'99 May20	1hr	south east of Hyogo	M3.4	
'00 Oct06	3.2hr	west of Tottori	M7.1	
'00 Nov16	1hr	New Ireland	M8	(No beam abort)
'01 Mar24	2.7hr	Geiyo	M6.4	

